Site Name		Lat/Long	Phase I Assessment		Phase II Assessment			Cleanup		Site Work Description	Reuse Status
	Community-Segment		Report	Cost	QAPP-SAP	Report	Cost	Report	Cost		
Twin Buttes Community Ctr.	Twin Buttes	LAT: 47°31'42.9"N LONG: 102°12'25.1"W LAT:47.528582 LONG: -102.206979	Dec-04	\$2.000						Burned building with debris	Assessments Completed - Site Clear up - Reuse Recreation
Lone Fight Store	Mandaree	LAT: 47.732 LONG: -102.674	2008	\$4,000		2008	\$21,000			burned building with debits	up - Neuse Neuseallon
2 Mandaree House 102	Mandaree	LAT: 47.7324252 LONG: -102.6741886	Sep-09	\$2,000	06/28/10	Aug-10	\$4,000	Aug-10	\$0	House demoed by EPA due to asbestos	ready for reuse
Mandaree House 109	Mandaree	LAT: 47.7328293 LONG: -102.6748323	Sep-09	\$2,000	06/28/10	Aug-10	\$4,000	Aug-10	\$0	House demoed by EPA due to asbestos	ready for reuse
4 Mandaree House 113	Mandaree	LAT: 47.7328293 LONG: -102.6750898 LAT: 47.731800	Sep-09	\$2,000	06/28/10	Aug-10	\$4,000	Aug-10	\$0	House demoed by EPA due to asbestos	ready for reuse
Solid Surfaces Co.	Mandaree	LAT: 47.731800 Long: -102.66910 LAT: 47.73259		NA		NA		Apr-06	\$0	EPA OSC Removal Action of Haz. Waste	ready for reuse
Air Force Homes Ridge Rd. (Home No. 1)	Mandaree	Long: -102.67270	Sep-09	\$2,000	06/28/10	Aug-10	\$6,000				
Air Force Homes Ridge Rd. 6 (Home No. 1) Air Force Homes Dakota Dr.	Mandaree	LAT: 47.73259 Long: -102.67270 LAT: 47.98441	Sep-09	\$2,000	06/28/10	Aug-10	\$6,000				
(Home No. 3)	New Town	Long: -102.49391	Sep-09	\$2,000	06/28/10	Aug-10	\$6,000				
Air Force Homes Dakota Dr. (Home No. 4)	New Town	LAT: 47.98441 Long: -102.49391	Sep-09	\$2,000	06/28/10	Aug-10	\$6,000				
Mandaree Pistol Range	Mandaree	LAT: 47.72714 Long: -102.67027	Sep-09	\$2,000	06/28/10	Aug-10	\$4,000			Assessed Mandaree Rifle Range	Phase I & II Assessment
10 Main St. Thrift Store	New Town	LAT: 47°58'40.5"N LONG: 102°29'54.3"W LAT: 47.977915 Long: -102.498416	Oct-11	\$2,000	06/28/10	Oct-11	\$2,000			Assessed Thrift Store for Asbestos	Ready for reuse- needs repair
41 Mart Dakota Gas Station	Now Town	LAT: 49° 58′ 45″ N LONG:	9000'38'3	\$4,000						Former Gas Station & Auto Repair Shop USTRAC (database) shows: Tank pull on 1/18/2008, "UST Site" report dated March 2008, 6/23/09 Groundwater report, 2/15/12 Groundwater report, 5/8/12 UST NFA letter from ND DOH	VOT. Comment

USTs Removed Site Eligibility Requested &

Site Eligibility Requested & Approved

Approved

Assessment of Suspected Asbestos

Abandoned Building - Former BIA police Station & garage. TAT-ED issued a NOV to the BIA. BIA to Clean up the Site Fall 2015.

TAT Brownfield Site Work Data

LAT: 49° 58' 45" N 102° 29'31" W

LAT: 47.6614 LONG: 101.8452

LAT: 47.661 101.845

New Town

White Shield

White Shield

6/6/2008

Sep-13

Sep-13

\$4,000

\$4,000

\$4,000

Aug-13

Aug-13

Sep-13

Sep-13

\$16,000

\$16,000

Updated: 3-6-2014

11 West Dakota Gas Station

13 Old BIA Police Station

12 Debris Site